

9-24-86  
INSP.

CERTIFIED MAIL:

EPA: P 447 526 757  
MDNR: P 447 526 758

November 12, 1986

Ms. Bonnie Eleder - 5HE-12  
Remedial Project Manager  
CERCLA Enforcement Section  
U. S. Environmental Protection Agency  
230 S. Dearborn Street  
Chicago, IL 60604

Director  
Michigan Department of  
Natural Resources  
P. O. Box 30028  
Lansing, MI 48909

To Whom It May Concern:

Subject: Consent Decree Action 80-73699

I have attached copy of the third 1986 Quarterly inspection of  
the Riverview site.

If there are any questions, please advise.

Yours very truly,



C. W. Axce  
General Manager - Wyandotte

mh  
enc.

RECEIVED

NOV 17 1986

U.S. EPA, REGION V  
WASTE MANAGEMENT DIVISION  
HAZARDOUS WASTE PROGRAM

US EPA RECORDS CENTER REGION 5



406830

**BASF Corporation** Chemicals Division

1609 Biddle Avenue, Wyandotte, Michigan 48192.

Cost Center No.

Sender:

**BASF**

P 447 526 757

Mrs. Bonnie Eleder - SHE-12  
Remedial Project Manager  
CERCLA Enforcement Section  
US EPA  
230 S. Dearborn  
Chicago, IL 60604

PREVENTIVE MAINTENANCE

EASF Corporation

TITLE: Riverview Property

SSO NO.: 110005 CC No.: 3058

INSPECTION FREQUENCY: 3 Months

INSPECTION DUE DATE: 09/30/86

Date Issued: 8/85

Date Revised: 11/85 - LTB

Folder No.: 1490

Sheet 1 of 9

EQ. CODE: 00-00

PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

THIS PM REQUIRES THE INSPECTOR TO LOOK AT MANY THINGS AND WALK OR DRIVE OVER A LARGE AREA. THE INSPECTOR SHOULD READ THIS PM COMPLETELY PRIOR TO MAKING THE INSPECTION SO THAT NO WASTED EFFORT HAS TO OCCUR "GOING BACK".

- 1. Inspect entire fence.
  - A. Fence must be completely intact, including 3 strands of barbed wire on top. All gates must be locked.

- I.A. Make a list of any broken barbed wire, broken or deformed fence, bent or damaged fence posts or rails, gate hinges, locks, etc.

All O.K.

Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 2 of 9

## PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

- B. Inspect signs on fence. Signs must face outward from property. The signs must be spaced at 100' intervals on all four sides of the property. The signs must be in good condition with 1-1/2" high letters.

WARNING  
KEEP OUT

MANAGED INDUSTRIAL WASTE DISPOSAL AREA

- II. Inspect vegetation from Jefferson/to the water and from the common property line with Firestone to the municipal ramp.

- A. Look for any "bare" areas (spots or areas which do not have plant life growing).

Plan. Bare areas are being reseeded  
during week of 11/4/87.

- B. Measure the height of the vegetation. As the vegetation is measured, look for areas where growth is stunted.

- I.B. 1. Are signs spaced every  
100 ft.? Yes\_\_\_ No X

2. Make a list of missing  
rusted, bent, illegible,  
etc., signs.

Signs on new fence will be in-  
stalled by 9/30/86. All old fence-  
ing signs are O.K.

- II.A. List "bare" areas. Describe  
size and location of bare  
spot.

At Main Gate 1 30' x 20' area at  
new fence and new drainage trench,  
bare spots range between 3 to 4  
75 ft. wide. Several 10 sq. ft.  
patches and 6 to 10 wheel ruts  
are bare along river fence.

- II.B. List the "average" height  
of the vegetation.

Average height between 6 and 8",  
with some 12" high patches along  
river fence.

Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 3 of 9

## PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

III. Inspect the shoreline for stability.

III. List any shoreline erosion, washing, other deterioration or accumulation of debris.

No shoreline erosion. A small accumulation of river debris on shore at high water line. To be cleaned up by 9/30/86.

IV. Review the integrity of the compacted clay cover.

A. Inspect the entire area for the physical condition of the surface.

IV.A. List any erosion, standing pools of water, weathering, change in drainage patterns, etc.

No erosion visible or drainage. Pattern changes are evident - several 8' x 10' pools of standing water in low areas at the river fence line.

B. Look for any deep-rooted vegetation (trees or other plant life which might or does have tap roots). Any vegetation which is taller than surrounding vegetation should be considered deep-rooted.

IV.B. List deep-rooted vegetation.

Several small areas (5 to 10 sq. ft.) of deep-rooted vegetation are growing on the N.W. and S.E. quadrant. An October weed spraying program is planned to eliminate them.

Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 4 of 9

## PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

V. Inspect the berm which is constructed along the common property line with Firestone. This berm is constructed to eliminate water flowing from the Firestone property onto the site.

V. Is the berm at least 6 inches above the level of the Firestone property at the property line?

Yes X No     

Is there any evidence of water flowing from the Firestone property onto the site?

Yes      No X

VI. Inspect the two concrete drainage ditches on the site, one through the center and one at the northeast corner.

VI.A. List any cracks in the concrete, leaking through the cracks, accumulated debris, standing water, etc.

No cracks in concrete - trench is approx. 2/3 full of water due to heavy rains during early part of this week and high river level.

B. There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

VI.B. List condition of each joint.

Joint 1: Good - dry.

Joint 2: Good - dry.

General Note: A technical investigation of joint leaks & future repairs is being conducted.

Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 5 of 9

## PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

VI. B. (Cont'd.) There are thirty (30) joints in the center ditch. Note condition of each joint. Is the joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint 4: Approx. 1/3 of joint is covered with off-colored water. Exposed joint good and dry. Joint repair being handled by Corp. Eng. Complete by April 1987.

Joint 6: Repaired joint coming apart and leaking off-colored water. Joint repair being handled by Corp. Eng. Complete by April 1987.

Joint 8: Dry - repaired joint coming apart and is damp. Joint repair being handled by Corp. Eng. Complete by April 1987.

Joint 10: Approx. 1/3 of joint is covered with water. Repaired joint is damp in exposed areas and coming apart. Joint repair being handled by Corp. Eng. Complete by 4/87.

VI.B. List condition of each joint.

Joint 3: Repaired joint leaking off-colored water at bottom of trench. Joint repairs being handled by Corp. Eng. Complete by April 1987.

Joint 5: Repaired joint coming apart and leaking off-colored water. Joint repair being handled by Corp. Eng. Complete by 4/87.

Joint 7: Approx. 1/3 of joint covered with water. Exposed joint dry and good. Joint repair being handled by Corp. Eng. Complete by 4/87.

Joint 9: Dry - repaired portion of joint coming apart and is damp. Joint repair being handled by Corp. Eng. Complete by 4/87.

Joint 11: Dry - good condition.

Folder No.: 1490

TITLE: Riverview Property

CC No. 3058

Sheet 6 of 9

## PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

VI. B. (Cont'd.) There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint 13: Approx. 2/3 of joint is covered w/water - leaking off-colored water and discoloring the clear water at bottom of trench; exposed joint O.K. Joint repair being handled by Corp. Eng. Complete By April 1987.

Joint 15: Approx. 2/3 of joint is covered w/water - bottom of trench has silt built up. Exposed joint O.K.

Joint 17: Approx. 3/4 of joint is covered w/clear water due to high river level - exposed joint O.K. A small amount of silt covers the bottom of the trench.

Joint 19: Approx. 3/4 of joint is covered w/clear water due to high river level - exposed joint O.K. A small amount of silt covers a part of the bottom of the trench.

VI.B. List condition of each joint.

Joint 12: Approx. 1/3 of joint is covered with water. Exposed repaired joint is damp. Joint repair being handled by Corp. Eng. Complete by 4/87.

Joint 14: Approx. 2/3 of joint covered w/water and silt at bottom of trench - exposed joint O.K. Joint repair being handled by Corp. Eng. Complete 4/87.

Joint 16: Approx. 2/3 of joint covered w/water - exposed repaired joint is damp. Joint repair being handled by Corp. Eng. Complete by 4/87.

Joint 18: Approx. 3/4 of joint covered w/clear water due to high river level - exposed joint O.K. Small amount of silt covers bottom of the trench.

Joint 20: Approx. 3/4 of joint covered w/clear water due to high river level - exposed joint O.K. Bottom of trench is silt covered.



Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 7 of 9

## PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

VI. B. (Cont'd.) There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint 22: Approx. 7/8 of joint covered w/clear water due to high river level - exposed joint O.K. Bottom of trench is silt covered.

Joint 24: Approx. 7/8 of joint covered w/clear water due to high river level - exposed joint O.K. Bottom of trench has small amount of silt.

Joint 26: Approx. 7/8 of joint covered w/clear water due to high river level - exposed joint O.K.

Joint 28: Joint entirely covered w/clear water due to high river level

VI.B. List condition of each joint.

Joint 21: Approx. 7/8 of joint covered w/clear water due to high river level. Exposed joint O.K. Bottom of trench is silt covered.

Joint 23: Approx. 7/8 of joint covered w/clear water due to high river level - exposed joint O.K. Bottom of trench is silt covered.

Joint 25: Approx. 7/8 of joint covered w/clear water due to high river level - exposed joint O.K.

Joint 27: Joint entirely covered w/clear water due to high river level. Approx. 2/3 of repaired joint has loose chalking. Joint repair being handled by Corp. Eng. Complete by 4/87.

Joint 29: Joint entirely covered w/clear water due to high river level.

Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 8 of 9

PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

VI. B. (Cont'd.) There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

VI.B. List condition of each joint.

Joint 30: Joint entirely covered w/clear water due to high river level.

There are four (4) joints in the north ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint A: Dry - good.

Joint B: Dry - good.

Joint C: Dry - good.

Joint D: Approx. 1/3 covered w/water due to high river level.

ENVIRONMENTAL

ENVIRONMENTAL

ENVIRONMENTAL

Folder No.: 1490

TITLE: Riverview Property

CC No.: 3058

Sheet 9 of 9

PROCEDURE

REPORT HERE - FINDINGS &  
ITEMS REPAIRED OR REQUIRED

VII. Inspect each of the nine (9) monitoring wells for  
integrity.

VII. List any problems with the  
wells.

35  
4D  
A - Locked - O.K.  
B - " - "  
C - " - "  
D - " - "  
-E - Pipe is lifting - Locked  
-F - " " " - Locked  
G - Locked - "  
H - " - "  
J - " - "  
J - " - "

Inspected by: D. J. Savage and W. Chavis

Date Inspected: 9/24/86

ENVIRONMENTAL

ENVIRONMENTAL

ENVIRONMENTAL